

Nov. 13: Worker at Peat Moss Site Dies from Crushing Injuries



A 40-year-old man died in an incident at a peat moss harvesting site. He suffered crushing injuries from a hydraulic conveyor. WorkSafeNB officers issued a stop-work order to prevent disruption of the scene and were investigating the incident.