Worker on Metal Ladder Electrocuted by Damaged Extension Cord



A worker was standing on an aluminum ladder while constructing a bus shelter. A damaged extension cord came into contact with the ladder, shocking him. He died from his injuries in the hospital. The CSST incident investigation report is available online [Govt. News Release, Feb. 20, 2014].